












Assembly Instructions

TOMORROW'S TOUCH-BASED TECHNOLOGY, TODAY...



Part List:



M6x10
I. 4pcs

M4x16 M5x16 M6x16
J. 4pcs/each

M5
K. 4pcs/each

M. M8x14x6pcs

N. M8x6pcs

O. M8x16x4pcs





P. M8x2pcs

Q. 1pc


R. 2pcs

S. M8x40x4pcs


T. M6x10x3pcs




1.




2.




3.




4.





5.




6.



7.



8.



Adjust torque... if necessary

Adjust height... if necessary